

# A case study of long-term geochemical evolution of coal waste rock drainage and its remediation

Adam Jarvis

Head of HERO Group  
Senior Lecturer, School of Civil Engineering & Geosciences, Newcastle University, UK




IMWA 2010, Nova Scotia, Canada

## The site and the problem



IMWA 2010, Nova Scotia, Canada

## The site and the problem



Main discharge point at outlet from culvert

IMWA 2010, Nova Scotia, Canada

## Discharge water quality

	Mean	Maximum	Minimum	n
pH	6.4	8.9	4.2	164
Conductivity (µS/cm)	6216	14030	280	147
Alkalinity (mg/L as CaCO <sub>3</sub> )	59	136	0	149
Iron (mg/L)	5.0	20.5	0.5	182
Manganese(mg/L)	3.3	8.6	0.4	180
Aluminium (mg/L)	4.7	13.6	0.1	171
Zinc (mg/L)	1.2	4.1	0.1	123
Calcium (mg/L)	203	408	47	117
Magnesium (mg/L)	64	141	8	117
Sodium (mg/L)	1091	3251	140	117
Potassium (mg/L)	132	505	17	116
Sulphate (mg/L)	717	1541	106	174
Chloride (mg/L)	1788	4535	220	154

IMWA 2010, Nova Scotia, Canada



## Wetland treatment system



- Discharge from waste rock pile caused discoloration of the local watercourse
- 500 m<sup>2</sup> compost treatment wetland system constructed in 1997
- Overall size of wetland constrained by land availability (a common issue in the UK)
- A charitable project
- Wetland system constructed in collaboration with the residents of the local village, Quaking Houses


IMWA 2010, Nova Scotia, Canada

## Wetland treatment performance



IMWA 2010, Nova Scotia, Canada


**Wetland treatment performance**



Deterioration in performance primarily driven by inundation of dead reed material within the system – clearly a maintenance issue

IMWA 2010, Nova Scotia, Canada


**Long-term evolution of waste rock drainage**



- Clear improvement in water quality over time
- Much quicker improvement than predicted by pyrite oxidation and dissolution modelling
- Result of partial capping of the heap in areas known to be acid-generating (and probably also natural re-vegetation of the heap)

IMWA 2010, Nova Scotia, Canada

**Long-term evolution of waste rock drainage**



- Since around 2003 drainage net-alkaline
- Change in water quality influenced renovation of wetland system – primary objective removal of marginally elevated iron concentrations

IMWA 2010, Nova Scotia, Canada

**Wetland system renovation**



Key issue during renovation was disposal of compost wetland substrate (above)

IMWA 2010, Nova Scotia, Canada

**Wetland system renovation**

- British Standard (BS) leachability tests showed substrate could be disposed of as 'inert' waste (concentrations below Waste Acceptance Criteria (WAC) as inert waste).
- Note that iron and aluminium not required determinants for leaching tests (but Fe present at ~ 60 000 mg/kg)
- Disposal as inert waste significantly reduced overall costs of renovation

Period	L/S Ratio	Cl <sup>-</sup>	SO <sub>4</sub> <sup>2-</sup>	Zn	As	Cd	Cr	Cu	Ni	Pb
6 hrs	A <sub>2</sub> (mg/kg dry matter)	694	1494	0.04						
18 hrs	A <sub>6</sub> (mg/kg dry matter)	661	2819	0.29	0.05	0.01	0.01	0.01	0.01	0.05
24 hrs	A <sub>10</sub> (mg/kg dry matter)	455	1996	0.08	0.100	0.02	0.02	0.0	0.02	0.10
	WAC limit (mg/kg) L/S <sub>10</sub>	800	6000	4	0.5	0.04	0.5 (total)	2	0.4	0.5

IMWA 2010, Nova Scotia, Canada

**Full life-cycle wetland costs**

- Original wetland cost approximately £60 000 to construct (~ CAN \$100 000)
- Renovation cost approximately £50 000
- Therefore over 8 years of operation cost was ~ £14 000 / annum
- No question that system would have performed for longer with basic maintenance programme in place e.g. reed clearance
- For other wetland systems costs may be significantly greater if other, potentially more eco-toxic, metals present in exhausted substrate

IMWA 2010, Nova Scotia, Canada

### ***Conclusions***

- Modestly-sized compost wetland successfully attenuated acidity and metals in waste rock drainage
- Improved maintenance programme would likely have extended lifetime of original system
- Land availability always an issue in UK, and therefore such passive systems always likely to need renovation at some point – cannot ignore / overlook this requirement
- Presence of potentially eco-toxic metals might significantly increase costs of renovation
- Selective capping of waste rock appears to have resulted in improved drainage quality, which should extend lifetime of renovated system, further reducing future costs

IMWA 2010, Nova Scotia, Canada